

Firmware Release Note



Model: C406x Series	Date: 7-Mar-2019
----------------------------	-------------------------

V6.00.07.02 FW addresses total of 5 issues.

- Major Changes

1. Fixed to support the GCP uses latest google specified certificates.
2. Fixed the performance mode power save mode to avoid HDD disk failure.
3. Fixed SMTP to work even when server supports only TLSv1.2
4. Fixed the WSD Install issue in Win10 for a specific version.
5. Fixed the Memory issue with mDNS

Please upgrade the FW with V6.00.07.02 if any one of the problems below need to be resolved.

Version	Category	TSP ID	Division	Change Description
V6.00.07.02 (7-Mar-2019)	Problem	-	-	Fixed to support the GCP uses latest google specified certificates.
	Problem	-	-	Fixed the performance mode power save mode to avoid HDD disk failure.
	Problem	-	-	Fixed SMTP to work even when server supports only TLSv1.2
	Problem	-	-	Fixed, when snmpcommunity.cgi is called SNMPv3 is getting disabled issue.
	Problem	-	-	Fixed the WSD Install issue in Win10 for a specific version.
	Problem	-	-	Fixed the Google Address Book issues
	Problem	-	-	Fixed the Memory issue with mDNS
	Problem	-	-	Fixed the issue of Box app Authentication.

Software Component Versions

System Firmware	V6.00.07.02
Main FW Version	V11.01.00.07.02_190224
XOA Web	1.4.26
UP	1.17.27_(20161201103902)
Engine Firmware	V1.00.94_170904
File System Version	V19.00.00.00.63
Scanner Version	V3.00.00.68_170329
Fax Version	V3.02
Boot Rom Version	V19.10.00.00.70_190207
UI Firmware	V5.39.00.45.00_18101014
HCF/SCF version	V3.00.05
Scan_Control	V1.00
Samsung Mobile Print	V11.43_170214
PCL5	V3.8.16_170216
PCLXL	V3.11.00.87_161108
PS/PDE/XPS	V3.6.16.01.61.01.98_170201

Image Quality Tables

EP	V406.00.01.53
Fuser	V0.35
Toner	N/A
TR	V0.35
Print CMS	V11.01_160926

Copy CMS	V8.00_161206
Scan CMS	V0.71
Print IEM	V1.4_161212
Copy IEM	V1.12_170207

Update dependency

N/A

Solution Compatibility Table

(C4060 : V6.00.07.02)

Category	Solution Name	Solution Version	V6.00.07.02	Verified F/W Version
BCPS	CloudConnectorCore	2.50.006	○	V6.00.05.00
	DocumentWorkflowCore	2.50.006	○	V6.00.05.00
	PrintingSecurityCore	2.50.006	○	V6.00.05.00
	SecureLoginCore	2.50.006	○	V6.00.05.00
	UsageTrackerCore	2.50.006	○	V6.00.05.00
	XOA-WEB Enabler	2.00.003	○	V6.00.03.12
ISV-XOA-E	Autostore	1.0.0 (Server : 7.0.0.18 (DRS:7.0.1.16, APD:7.0.1.10(Build:20160328-1)))	○	V6.00.03.12
	Equitrac	1.1.0.136 (Server : 5.6.25.5109)	○	V6.00.03.12
	Follow2Print	1.0.12 (Server : docuForm-Mercury 8.32)	○	V6.00.06.00
	Geniusbytes MyMFP	2.14.10.3 (Server : 2.13.10)	○	V6.00.03.12
	MyQ Embedded Terminal	5.3.1 (Server : 5.3.0.137)	○	V6.00.03.12
	Omtool AccuRoute	1.0.0.689 (Server : 2013(Build 5))	○	V6.00.03.12
	PaperCut	1.1.0 (Server : 16.0 (Build 35320))	○	V6.00.03.12
	PrintFleet Cloud Embedded DC	1.1.249 (Server : 3.6)	○	V6.00.03.12
	Ringdale FollowMe	1.1.2.9 (Server : 6.1.0.103)	○	V6.00.03.12
	SafeCom	010.24.21 (Server : 10.52.7.2(S82070.520*07))	○	V6.00.03.12
	SafeQ Embedded Terminal	1.0.0 (Server : C.0.9.001)	○	V6.00.03.12
	Scanner Vision	1.0.6 (Server : 6.2.0.270)	○	V6.00.03.12
	Scanshare Essentials	1.5.17.169 (Server : 4.4.0.5)	○	V6.00.03.12
Ubiquitech Easy & VDMS	1.4.0-beta12 (Server : 3.4.0-rel)	○	V6.00.03.12	
PrinterOn	PrinterOn Branded Agent	2.01.005	○	V6.00.03.12

○ A solution has been verified and MUST be compatible with the releasing F/W version.

○ Previously the supported solutions have been tested and verified with the version specified in the "Verified F/W version" row in the table. The required test has been conducted on this FW version to ensure the backward compatibility with "Verified F/W version".

Release History

Version	Category	TSP ID	Division	Change Description
V6.00.06.00 (7-Sep-2017)	Fixed issue	TP16A0E430	SEBN	Fixed an issue of printing data being corrupted from PC usb cables when the machine sleeps
	Fixed issue	-	-	Fixed wrong display of maximum life of the ADF roller and the ADF retard roller in the service mode. They were displayed as 50K but both should be 100K.
V6.00.05.00 (16-Aug-2017)	Fixed issue	TP17607P	SEG	Fixed issue of MSOK Error, S1-2521, by damaged contents when HDD encryption is enabled. If you have S1-2521, please refer Tech Tip PRT-T1742 from BTSP.
	Fixed issue	-	-	Fixed a paper jam issue by chattering of registration sensor.
V6.00.04.00 (16-May-2017)	Fixed issue	TP16A0E4	SEBN	Fixed a problem of being displayed as offline in printer driver spooler when the device is in power save mode (Status Code: S2-3313).
	Requirement	-	DEV	Raise high temperature threshold for S1-1113 error (CPU high temperature display error) from 90°C to 100°C. (Operating temperature is 125°C according to CPU Spec)
V6.00.03.12 (10-Apr-2017)	First version	-	-	First release